And the second of the second o

OUT56077

•	Ε.	^	D	127	T	7	an	CAA	27
•	Ľ.	U	ĸ	E	- 1	ာ	WZ.	204	WL

1965 JUN 30 20 53 Z

PRIORITY |

4862

25X1

25X1

Act.

IDEALIST

ATTENTION:

SUBJECT: EVALUATION OF MISSION C325C

1. CAMERA 119 WAS USED IN MISSION C325C FLOWN ON 28 MAY 1965.

PROCESSING WAS ACCOMPLISHED IN THE FIELD.

1 JUL 1965

COPIES RECEIVED.

Cy No.

Office

NSA-LO DIA-AP

File

- 2. ORIGINAL NEGATIVE:
 - A. EXPOSURE WAS ADEQUATE AND THE RESOLUTION WAS GOOD.
- B. 9R SIDE: ROLLER CHATTER AND EDGE STATIC IS PRESENT ALONG ADMIN SEC BR THE INBOARD EDGE THROUGHOUT THE MISSION. EDGE FOG IS APPARENT P&DS CSD INTERMITTENTLY ALONG THE OUTBOARD EDGE. A STREAK OF FOG IS PRESENT IN FRAMES 188 TO 190. A BAND OF FOG 1.8" WIDE ALONG THE INBOARD **PSD** PSD-ICB EDGE IS IN FRAMES 191 TO 197. BOTH OF THESE TERMINATE IN FRAMES 2 TID 202 TO 210 WHICH ARE COMPLETELY FOGGED. HEAT SPLICES ARE PRESENT PAG BETWEEN FRAMES 252/253, 526/527, 792/793 AND 1197/1198. DIAXX-4 SPAD

C. 9L SIDE: ROLLER CHATTER ON THE INBOARD EDGE STARTS ON FRAME 1 AND CONTINUES THROUGH THE MISSION. ON THE OUTBOARD EDGE ONLY THE FIRST 30 PERCENT IS AFFECTED. FOG ALONG THE OUTBOARD EDGE IS APPARENT IN FRAMES 288 TO 291. POSSIBLE EMULSION DIGS OR BLISTERS ARE PRESENT INTERMITTENTLY. HEAT SPLICES ARE BETWEEN FRAMES 265/266, 539/540, 805/806 AND 1197/1198. THERE IS A MANUFACTURER'S SPLICE IN FRAME 261.

D. BOTH SIDES: EDGE FOG APPEARS INTERMITTENTLY ALONG THE





OUTBOARD EDGE. THE LAST TITLED FRAME IS 1200.

- E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS.
- 3. POSITIVE:
 - A. PI SUITABILITY IS GOOD.
 - B. PRINTING AND PROCESSING WAS ADEQUATE.
 - C. CLOUD COVER IS APPROXIMATELY 35 PERCENT.

SECRET

-- END OF MESSAGE--